

## SSO Notification List

March 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/1/2021	3912 Foster Ave	21224	Sand, Gravel, Rocks, Structural	Wet	N/A	0	Gray water observed in the rear alleyway.	4	Ran 12 ft of electric cable through the lateral; determined structural damage exists in the pipe.	Line will be repaired to restore regular functionality.	914563
2	3/3/2021	4603 Briarclift Rd	21229	Structural	Wet	N/A	11555	Sewer discharging into the stream from hole in the side of pipe.	23,110	Point repair was performed to restore the system to regular functionality.	Abatement confirmed via Office of Compliance and Research.	914886
3	3/3/2021	4213 Audrey Ave	21225	Rags	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and determined the lateral is clear.	915013
4	3/4/2021	5701 Newbury St	21209	Rags, Roots	Wet	N/A	0	Gray water observed at the side of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is flowing freely; CCTV inspection will be performed in the future.	915178
5	3/4/2021	412 George St	21201	Structural	Dry	N/A	0	Gray water observed at the side of the property.	1	Ran 9 ft of electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will be conducted to determine cause.	915330
6	3/4/2021	2638 Miles Ave	21211	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	915121
7	3/4/2021	2715 Beethoven Ave	21207	Grease, Trash	Dry	N/A	0	Gray water observed around the manhole.	3	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the line is flowing freely; CCTV inspection will be performed.	915286
8	3/5/2021	2900 Belmont Ave	21216	Rags, Unknown	Dry	N/A	0	Gray water and paper observed at the rear of the property.	3	Ran 45 ft of electric cable through the lateral; no blockage was encountered.	Flushed and cleaned the mainline. CCTV inspection will be performed on the lateral.	915372
9	3/5/2021	2819 Goodwood Rd	21214	Rags	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed a lateral CCTV inspection and determined the line is clear.	915448
10	3/7/2021	3107 E Fairmount Ave	21224	Rags	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and determined the lateral is now clear.	915671
11	3/7/2021	2012 E 31st St	21218	Rags, Grease, Trash	Dry	Herring Run	146	Gray water escaping the manhole and entering nearby storm drain.	292	Relieved mainline choke with 350 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV inspection will be performed in the future.	915710
12	3/8/2021	932 Seagull Ave - (Private)	21225	Rags, Grease, Trash	Dry	N/A	83	Gray water escaping private manhole and entering nearby storm drain.	[166]	DPW assisted private system by relieving mainline choke with 175 ft of pressure hose.	Confirmed mainline is clear.	915786
13	3/8/2021	2023 Etting St	21217	Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	1	Unable to access the lateral; cleaned the surrounding area.	Advised consumer to install a functioning cleanout so work can be performed.	915849
14	3/8/2021	2419 Brentwood Ave	21218	Unknown	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran 43 ft of electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will be performed to determine the cause.	915872
15	3/8/2021	2455 McCulloh St	21217	Unknown	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran 45 ft of electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will be performed to determine a cause and course of action.	915880
16	3/8/2021	2300 Frederick Ave	21223	Rags, Roots, Grease, Trash	Dry	Gwynns Falls	840	Heavy gray water escaping the manhole.	1,680	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is flowing freely; CCTV inspection will be performed in the future.	915952
17	3/9/2021	4304 Glenmore Ave	21206	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed in the future to ensure all obstructions were removed.	916084
18	3/9/2021	921 N Arlington St	21217	Rags, Roots, Trash	Dry	N/A	91	Gray water escaping the manhole in the rear alley.	182	Relieved mainline choke with 125 ft of pressure hose.	Confirmed the mainline is flowing freely; CCTV inspection will be performed in the future.	916003
19	3/10/2021	1412 N Luzerne Ave	21213	Trash	Dry	N/A	0	Gray water and paper observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection; advised consumer to install a cap on cleanout.	916189
20	3/10/2021	4010 Bateman Ave	21216	Rags, Roots, Trash	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned the 8" mainline.	916386

## SSO Notification List

March 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	3/10/2021	1933 McCulloh St	21217	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	Lateral CCTV inspection will be performed to confirm line is clear.	916365
22	3/10/2021	5621 Belle Ave	21207	Roots	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed a CCTV inspection which indicated the lateral is now clear.	916403
23	3/11/2021	4314 Mainfield Ave	21214	Roots, Trash	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results determined the lateral is clear.	916522
24	3/11/2021	3729 Elm Ave	21211	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed lateral is clear. CCTV inspection and mainline cleaning will be performed.	916544
25	3/11/2021	3379 Saint Benedict St	21229	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	916490
26	3/11/2021	1203 Mosher St	21217	Sand, Gravel, Rocks, Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran 10 ft of electric cable through the house connection; blockage remained.	Further investigation, including CCTV inspection and lateral launch, will take place.	916638
27	3/12/2021	525 Hurley Ave	21223	Unknown	Dry	N/A	0	Gray water observed in the surrounding area.	5	Contractors arrived on site and pumped down the surcharge.	Utilities in this area will be upgraded. Contractors are engaged to monitor the situation.	916824
28	3/12/2021	6 Boulder Ln	21210	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole in the street.	4	Relieved 4" mainline choke with 400 ft of pressure hose.	Confirmed mainline is now flowing freely; CCTV inspection will be performed.	916851
29	3/12/2021	3030 Poplar Ter	21216	Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Inspected lateral and mainline; confirmed both are clear.	916860
30	3/12/2021	1911 W Mulberry St	21223	Trash	Dry	N/A	0	Gray water observed in the rear alley.	2	Relieved house connection choke with 45 ft of electric cable.	Performed a CCTV inspection and determined the lateral and mainline are clear.	916739
31	3/12/2021	1403 John St	21217	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with electric cable.	Advised consumer to replace older-style trap. Flushed and cleaned the mainline.	916841
32	3/13/2021	318 S Robinson St	21224	Rags	Dry	N/A	0	Gray water and debris observed at the rear of the property.	1	Advised consumer to upgrade to a modern cleanout so that work can be performed on lateral.	Flushed and cleaned the mainline.	916892
33	3/13/2021	4010 Bateman Ave	21216	Roots	Dry	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Cleaned the mainline and confirmed lateral is clear.	916895
34	3/13/2021	3 N Decker Ave	21224	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	916897
35	3/14/2021	2909 Whitney Ave	21215	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 75 ft of electric cable.	Performed a CCTV inspection and results confirmed the line is clear.	916965
36	3/15/2021	2735 Rayner Ave	21216	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed obstructions were removed from the line.	917137
37	3/16/2021	402 S Clinton St	21224	Sand, Gravel, Rocks, Structural, Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran 9 ft of electric cable through the lateral; determined structural damage exists.	Lateral will be repaired. Bypass pump may be required while repairs take place.	917544
38	3/17/2021	3404 Cotwood Pl	21215	Rags, Roots, Trash	Dry	Jones Falls	78	Heavy gray water escaping the manhole.	390	Relieved mainline choke with 125 ft of pressure hose.	Confirmed the mainline is now flowing freely; CCTV inspection will be performed in the future.	917635
39	3/17/2021	513 N Belnord Ave	21205	Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with electric cable.	Confirmed lateral is clear.	917766
40	3/18/2021	6406 Loch Raven Blvd	21239	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection and results showed the line to be clear.	918055

## SSO Notification List

March 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
41	3/19/2021	2829 Overland Ave	21214	Trash, Unknown	Wet	N/A	0	Gray water observed at the front of the property.	1	Advised consumer to remove cleanout cap and install connection closer to the city line.	CCTV inspection will be performed.	918124
42	3/19/2021	2554 Arunah Ave	21216	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection to confirm lateral is clear at this time.	918149
43	3/19/2021	5813 Loch Raven Blvd	21239	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 40 ft of electric cable.	Performed lateral CCTV inspection to confirm the line is now clear.	918229
44	3/19/2021	1533 Northbourne Rd	21239	Roots	Wet	N/A	0	Gray water and paper observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is now clear.	918237
45	3/19/2021	4100 Fairview Ave	21216	Rags, Trash	Wet	Gwynns Falls	381	Gray water escaping the manhole.	381	Relieved mainline choke with 100 ft of pressure hose.	Confirmed the mainline is now flowing freely; CCTV inspection will be performed in the future.	918273
46	3/20/2021	413 S Robinson St	21224	Trash, Unknown	Wet	N/A	0	Gray water observed at the rear of the property.	1	Ran 3 ft of electric cable; blockage remained.	Further investigation, including a CCTV inspection, will be performed to determine a cause.	918270
47	3/20/2021	318 E 26th St	21218	Rags, Roots, Grease, Trash	Wet	Jones Falls	0	Gray water observed at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is now clear; performed mainline cleaning.	918360
48	3/21/2021	509 Westgate Rd	21229	Rags, Roots, Grease, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results indicated the lateral is now clear.	918412
49	3/22/2021	3517 Oakmont Ave	21215	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed; advised consumer to replace cleanout cap.	918487
50	3/22/2021	408 Poplar Grove St	21223	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Checked the lateral and mainline and confirmed both are clear at this time.	918623
51	3/22/2021	6434 O'Donnell St	21224	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole.	7	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed in order to confirm mainline is clear.	918652
52	3/22/2021	5207 Putney Way	21212	Rags, Trash	Dry	N/A	164	Gray water escaping the manhole near the sidewalk.	82	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed in the future to ensure all obstructions were removed from pipe.	918686
53	3/22/2021	2752 Kinsey Ave	21223	Sand, Gravel, Rocks, Structural	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran 19 ft of electric cable through the lateral; determined structural damage exists.	House connection will be repaired. Regular functionality will be restored.	918576
54	3/24/2021	2820 W North Ave	21216	Trash	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable using various cutters to clear blockage.	Will view CCTV inspection to verify if any damage to lateral exists that may cause an SSO.	919366
55	3/24/2021	Hunter St & E Eager St	21202	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the manhole.	8	Relieved mainline choke with 50 ft of pressure hose.	Confirmed mainline is now flowing freely; CCTV inspection will be performed.	919420
56	3/24/2021	1600 Pentwood Rd	21239	Rags, Rain, Trash	Wet	Herring Run	0	Heavy gray water observed around the manhole.	25	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed to confirm obstructions were removed.	919501
57	3/24/2021	2829 Overland Ave	21214	Rags	Wet	N/A	0	Gray water and debris observed around the rear cleanout.	1	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection and results determined the line is clear.	919512
58	3/24/2021	5713 Edgepark Rd	21239	Rags, Trash	Wet	Herring Run	242	Gray water escaping the manhole.	484	Relieved mainline choke with 250 ft of pressure hose.	Performed CCTV inspection and confirmed the line is now clear.	919585
59	3/24/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	405	Structure monitored by metering equipment in the pipe. Not visually observed.	2,359,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
60	3/24/2021	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	300	Structure monitored by metering equipment in the pipe. Not visually observed.	483,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	

## SSO Notification List

March 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
61	3/24/2021	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	115	Heavy gray water escaping manhole.	48,000	Overflow subsided following heavy rain event.	Capital improvement projects are being implemented to prevent this overflow from reoccurring.	
62	3/24/2021	3900 Belair Rd	21206	Rain	Wet	Herring Run	270	Manhole adjacent to creek overflowed due to heavy rain.	2,366,000	Overflow subsided following heavy rain event.	Overflow will be prevented after completion of capital improvement projects.	
63	3/26/2021	1138 E Northern Pkwy	21239	Rags, Trash	Wet	Herring Run	700	Gray water escaping the manhole in the street.	1,400	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is flowing freely at this time; future CCTV inspection will be performed.	919992
64	3/27/2021	5504 Wexford Rd - (Private)	21209	Structural, Unknown	Wet	N/A	0	Gray water observed around the cleanout.	[1]	Ran electric cable through the lateral; structural damage exists on consumer's side.	Advised consumer to have a private plumber address their issue.	920103
65	3/28/2021	1526 Pentwood Rd	21239	Rags, Grease	Wet	N/A	0	Gray water observed around the manhole in the street.	3	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed in the future to confirm all obstructions were removed from pipe.	920135
66	3/30/2021	S Dukeland St & Wilkens Ave	21223	Rags, Rain, Trash	Wet	Gwynns Falls	0	Heavy gray water observed around the manhole.	15	Line appears to have surcharged due to recent heavy rain event.	CCTV inspection will be performed for more information.	921022
67	3/30/2021	3515 Menlo Dr	21215	Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Ran 45 ft of electric cable through the lateral.	CCTV inspection will be performed to determine if more blockage exists.	921578
				# WWO	26			TOTAL	5,284,133	UNDER 100 GALLONS	53	